SAUTER CATALOGUE 2019

Load cells SAUTER CT Q1 · CT P1





Fig. shows optional accessory load corner SAUTER CE P4022

CT Q1

Measuring cells made from stainless steel



- Accuracy in accordance with OIML R60 C3
- CE and RoHS compliant
- Dust and spray protection to IP68/IP69K (in accordance with EN 60529), welded to create a hermetic seal
- Stainless steel
- Area of application: Measuring mass as well
 as compressive force in harsh environments
- Suitable for platform scales, weigh hoppers, flush-mounted floor scales and other weighing devices
- 6-wire connection
- Nominal sensitivity: 2 mV/V
- · Note: EX version on request

Model	Nominal load	
SAUTER	kg	
CT 300-3Q1	300	
CT 500-3Q1	500	
CT 750-3Q1	750	
CT 1000-3Q1	1000	
CT 1500-3Q1	1500	
CT 2000-3Q1	2000	
CT 3000-3Q1	3000	
CT 5000-3Q1	5000	
CT 7500-3Q1	7500	
CT 10000-3Q1	10000	





Fig. shows optional accessory load corner SAUTER CE P4022

CT P1

Measuring cells made from stainless steel



- Accuracy in accordance with OIML R60 C3
- CE and RoHS compliant
- Dust and spray protection to IP67 (in accordance with EN 60529), welded to create a hermetic seal
- Nickel-plated steel
- Area of application: Measuring mass as well
 as compressive force in harsh environments
- Suitable for platform scales, weigh hoppers, flush-mounted floor scales and other weighing devices
- 4-wire connection
- Nominal sensitivity: 3 mV/V
- Note: EX version, 6-wire connection and accuracy class C4 or C5 on request

Model	Nominal load	
SAUTER	kg	
CT 500-3P1	500	
CT 1000-3P1	1000	
CT 1500-3P1	1500	
CT 2500-3P1	2500	
CT 3000-3P1	3000	
CT 5000-3P1	5000	
CT 10000-3P1	10000	

Note: Further details and plenty of further accessories see internet



SAUTER CATALOGUE 2019

Pictograms



Adjusting program (CAL): For quick setting of the instrument's accuracy. External adjusting weight required.



Calibration block:

standard for adjusting or correcting the measuring device.



Peak hold function: capturing a peak value within a measuring process.



Scan mode: continuous capture and display of measurements



Push and Pull:

the measuring device can capture tension and compression forces.



Length measurement:

captures the geometric dimensions of a test object or the movement during a test process.



Focus function:

increases the measuring accuracy of a device within a defined measuring range.



Internal memory:

to save measurements in the device memory.



Data interface RS-232: bidirectional, for connection of printer



and PC.



Data interface USB:

To connect the measuring instrument to a printer, PC or other peripheral devices.




Data interface Infrared:

To transfer data from the measuring instrument to a printer, PC or other peripheral devices.



Control outputs (optocoupler, digital I/O): to connect relays, signal lamps, valves, etc.



to connect a suitable peripheral device for ANALOG analogue processing of the measurements



Statistics: using the saved values, the device calculates TATISTIC statistical data, such as average value, standard deviation etc.



PC Software: to transfer the measurement data from the device to a PC.



Printer:

a printer can be connected to the device to print out the measurement data.

GLP/ISO record keeping: GLP of measurement data with date, time and





Measuring units: Weighing units can be switched to e.g. non-metric at the touch of a key. Please refer to website for more details.

serial number. Only with SAUTER printers




Measuring with tolerance range (limit-setting function): Upper and lower limiting can be programmed

individually. The process is supported by an audible or visual signal, see the relevant model

ZERO: +0+ ZERO

Resets the display to "0".



Rechargeable battery pack:

rechargeable set.

Mains adapter:



ACCU

- E
230 V

Power supply: Integrated, 230V/50Hz in EU. More standards e.g. GB, AUS or USA on request.

230V/50Hz in standard version for EU. On

request GB, AUS or USA version available.



Motorised drive:

The mechanical movement is carried out by a electric motor.



Motorised drive:

The mechanical movement is carried out by a synchronous motor (stepper).



Fast-Move:

the total length of travel can be covered by a single lever movement.



DAkkS calibration possible:

The time required for DAkkS calibration is shown in days in the pictogram.



Factory calibration:

The time required for factory calibration is specified in the pictogram.



Package shipment:

The time required for internal shipping preparations is shown in days in the pictogram.



Pallet shipment:

The time required for internal shipping preparations is shown in days in the pictogram.

Your KERN specialist dealer:



