Weller®

## Operating Instruction
WX Foot switch

Order No. T0058764746

Requirements:

WXD 2 or WXA 2 soldering station and WXR 3 rework station: Firmware version 065 or higher

Networkconfiguration:

WXD 2 / WXA 2 / WXR 3

Fußschalter
Foot switch
Contact Pédale
Comando a pedale
Pedal interruptor
Interruptor de pé   On

WX solder station*   WXR 3 rework station

Replacement cable
T0058764710

Foot switch (not pushed)

Foot switch (pushed)

*(Note: WX foot switch is only connectable to FRONT RS232 PORT)

Printed in Germany. T005 57 365 00 / 11.2014

www.weller-tools.com