

Manual test stand SAUTER TVL



Manual test stand for highly accurate tensile and compressive force measurements, with length measurement

Features

- · For vertical and horizontal use
- Precise measurement result
- **High level of security** with repeated measurements
- Large base plate with high versatility of fastening objects
- Can be used for force gauges up to 500 N (not included)
- Hook with M6 thread as standard
- · Digital length meter SAUTER LA standard:
 - Measuring range: max. 200 mm
 - Readout: 0,01 mm
- Zero setting possible
- Pre-length can be set manually

Technical data

- \bullet Max travel from base plate: 297 mm
- Travel distance per knob rotation (stroke per one turn): 3,1 mm
- Overall dimensions W×D×H 151×234×465 mm
- Net weight approx. 8,3 kg

STANDARD	
SCALE	1 DAY

Model	Measuring range	
SAUTER	[Max] N	
TVL.	500	



Pictograms



Adjusting program (CAL):

For quick setting of the instrument's accuracy. External adjusting weight required.



Calibration block:

standard for adjusting or correcting the measuring device.



Peak hold function:

capturing a peak value within a measuring process.



Scan mode:

continuous capture and display of measurements



Push and Pull:

the measuring device can capture tension and compression forces.



Length measurement:

captures the geometric dimensions of a test object or the movement during a test process.



Focus function:

increases the measuring accuracy of a device within a defined measuring range.



Internal memory:

to save measurements in the device memory.



Data interface RS-232:

bidirectional, for connection of printer and PC.



Data interface USB:

To connect the measuring instrument to a printer, PC or other peripheral devices.



Data interface Infrared:

To transfer data from the measuring instrument to a printer, PC or other peripheral devices.



Control outputs (optocoupler, digital I/O):

to connect relays, signal lamps, valves, etc.



Analogue interface:

to connect a suitable peripheral device for analogue processing of the measurements



Statistics

using the saved values, the device calculates statistical data, such as average value, standard deviation etc.



PC Software:

to transfer the measurement data from the device to a PC.



Printer:

a printer can be connected to the device to print out the measurement data.



GLP/ISO record keeping:

of measurement data with date, time and serial number. Only with SAUTER printers



Measuring units:

Weighing units can be switched to e.g. non-metric at the touch of a key. Please refer to website for more details.



Measuring with tolerance range (limit-setting function):

Upper and lower limiting can be programmed individually. The process is supported by an audible or visual signal, see the relevant model



ZERO

ZERO:

Resets the display to "0".



Battery operation:

Ready for battery operation. The battery type is specified for each device.



Rechargeable battery pack:

rechargeable set.



Mains adapter:

230V/50Hz in standard version for EU. On request GB, AUS or USA version available.



Power supply:

Integrated, 230V/50Hz in EU. More standards e.g. GB, AUS or USA on request.



Motorised drive:

The mechanical movement is carried out by a electric motor.



Motorised drive:

The mechanical movement is carried out by a synchronous motor (stepper).



Fast-Move:

the total length of travel can be covered by a single lever movement.



DAkkS calibration possible:

The time required for DAkkS calibration is shown in days in the pictogram.



Factory calibration:

The time required for factory calibration is specified in the pictogram.



Package shipment:

The time required for internal shipping preparations is shown in days in the pictogram.



Pallet shipment:

The time required for internal shipping preparations is shown in days in the pictogram.

Your KERN specialist dealer: